

October 29, 2019

Ohio Environmental Protection Agency Division of Air Pollution Control Southeast District Office 2195 Front Street Logan, Ohio 43138 Via eBusiness

Re: NSPS 0000a Annual Compliance Report

August 2, 2018 through August 2, 2019 Ohio River System - REX Booster Station

#### Dear Sirs:

Ohio River System, LLC is submitting this letter to meet the annual reporting requirement of New Source Performance Standard 40 CFR 60, Subpart 0000a (NSPS 0000a) for affected facilities owned/operated at the REX Booster Station. The REX Booster Station is located in Monroe County, Ohio. The NSPS 0000a affected facility is the "collection of fugitive emissions components at a compressor station".

The report contained in the following sections covers the compliance period from August 2, 2018 through August 2, 2019.

### I. General Information (§60.5420a(b)(1))

(1) The company name and address of the affected facility.

Mailing Address: 6051 Wallace Rd Ext., Suite 300, Wexford, PA 15090 Facility Location: REX Booster Facility, 52001 Township Highway 964, Powhatan Point, Monroe County, Ohio (Latitude: 39.83583, Longitude: -80.87425)

(2) An identification of each affected facility being included in the annual report.

This report includes the following NSPS 0000a affected facilities: Collection of fugitive emissions components at a compressor station.

(3) Beginning and ending dates of the reporting period.

This report covers the compliance period from August 2, 2018 through August 2, 2019.

(4) Certification by a responsible official of truth, accuracy, and completeness

Certification statement included at closing of this letter.

### II. Collection of fugitive emissions components at a compressor station (§60.5420a(b)(7))

See attached survey summary table and records of leak detection and repair (LDAR).

### III. RECIPROCATING COMPRESSORS (§60.5420a(b)(4))

(1) The cumulative number of hours of operation or the number of months since initial startup, since October 15, 2012, or since the previous reciprocating compressor rod packing replacement, whichever is later.

No NSPS 0000a Reciprocating Compressors at the compressor station.

(2) Records of deviations that occurred during the reporting period.

No deviations occurred during the reporting period.

### IV. PNEUMATIC CONTROLLERS (§60.5420a(b)(5))

(1) An identification of each pneumatic controller constructed, modified or reconstructed during the reporting period, including the identification information specified in §60.5390(b)(2) or (c)(2).

ORS did not commence construction of any gas-actuated continuous bleed pneumatic controller affected facilities during the reporting period.

(2) If applicable documentation that the use of pneumatic controller affected facilities with a natural gas bleed greater than 6 standard cubic feet per hour are required and the reasons why.

ORS did not commence construction for any gas-actuated continuous bleed pneumatic controllers utilizing the functional need exemption of 40 CFR 60.5390(a) during the reporting period.

(3) Records of deviations that occurred during the reporting period.

No deviations occurred during the reporting period.

Page 3 of 3 October 29, 2019

Should you have any questions or require additional information, please contact Doug Frisco at (570) 505-3700 or Patty Centofanti of Trinity Consultants at (412) 538-8038.

~~~~~~~~~

This certification shall state that, based on information and belief formed after reasonable inquiry, the statements and information in the document are true, accurate, and complete.

Sincerely,

Stephen Schuman
Stephen D. Schuman

VP Operations - East Division

cc: US EPA Region V, Air Protection Division

Office of Air Enforcement & Compliance

Ralph Metcalfe Federal Building

77 West Jackson Boulevard, Chicago, IL 60604-3511

Via email: 'R5AirEnforcement@epa.gov'

# List of Affected Facilities §60.5420a(b)

|                     |                       |           |            |       |        |                         |           |                             | <br>Affecte | ed Facilities |                                                                   |                                                                             |
|---------------------|-----------------------|-----------|------------|-------|--------|-------------------------|-----------|-----------------------------|-------------|---------------|-------------------------------------------------------------------|-----------------------------------------------------------------------------|
| Facility Name       | Legal Entity          | Latitude  | Longitude  | State | County | Municipality            | Region    | Reciprocating<br>Compressor |             | Storage       | Group of<br>Equipment<br>within a<br>Process<br>Unit <sup>1</sup> | Collection of<br>Fugitive Emission<br>Components at a<br>Compressor Station |
| REX Booster Station | Ohio River System LLC | 39.835827 | -80.874245 | Ohio  | Monroe | Switzerland<br>Township | OEPA SEDO |                             | <br>        |               |                                                                   | X                                                                           |

# Collection of Fugitive Emissions Components at a Compressor Station $_{\$60.5420a(b)(7)}$

| Facility Name          | Legal Entity         | Date<br>(b)(7)(i) | Beginning<br>Time<br>(b)(7)(ii) | End Time<br>(b)(7)(ii) | Name of OGI<br>Operator<br>(b)(7)(iii) | Training and Experience of OGI<br>Operator<br>(b)(7)(iii)                                                                                                                              | Ambient<br>Temperature, Sky<br>Conditions and<br>Maximum Wind<br>Speed<br>(b)(7)(iv) | Monitoring<br>Instrument<br>(b)(7)(v)  | Deviations<br>(or Statement o<br>No Deviations)<br>(b)(7)(vi) |                                                                                                                                    | Number and Type of<br>Components Not<br>Repaired as Required<br>(b)(7)(viii)                                                                                                                                      | Number and Type of DTM & UTM Components Monitored (b)(7)(ix) | Date of<br>Successful Leak<br>Repairs<br>(b)(7)(x)      | Number and<br>Type of<br>Components<br>Placed on DOR<br>(b)(7)(xi) | Explanation for<br>DOR<br>(b)(7)(xi) | Type of Instrument Used to Resurvey a Repaired Component (not during the initial finding)  | Comments            |
|------------------------|----------------------|-------------------|---------------------------------|------------------------|----------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|----------------------------------------|---------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------|---------------------------------------------------------|--------------------------------------------------------------------|--------------------------------------|--------------------------------------------------------------------------------------------|---------------------|
| REX Booster<br>Station | Ohio River<br>System | 9/13/2018         | 10:05 AM                        | 11:30 AM               | ŕ                                      | Trained by an ITC Certified<br>Thermographe, less than one (1)<br>year of production/midstream<br>surveying experience (including<br>approx. 10 natural gas facility<br>inspections)   | 76F, Partly Cloudy,<br>4.3 mph                                                       | FLIR, GFx320<br>Serial No.<br>44401371 | No Deviations                                                 | Leak #1: 204 Separator,<br>located on gauge                                                                                        | Leak was repaired and<br>verified within 30 days.<br>Re-taped and Tightened                                                                                                                                       | Not Applicable                                               | Leak was<br>repaired and<br>verified on<br>9/14/2018    | None                                                               | Not applicable                       | Method 21,<br>Section 8.3.3.1,<br>Soap Test                                                | See footnote 2      |
| REX Booster<br>Station | Ohio River<br>System | 12/10/2018        | 8:55 AM                         | 10:25 AM               | ·                                      | Trained by an ITC Certified<br>Thermographer. Less<br>than one (1) year of<br>production/midstream<br>surveying experience (including<br>over 60 natural gas<br>facility inspections). | 25F, Overcast, 2.3<br>mph                                                            | FLIR, GFx320<br>Serial No.<br>44401371 | No Deviations                                                 | Leak #1: Connector; plug on<br>relief<br>Leak #2: Connector; oil level<br>sight glass - top nipple<br>connection                   | repaired and verified                                                                                                                                                                                             | Not Applicable                                               | Leaks were<br>repaired and<br>verified on<br>12/11/2018 | None                                                               | Not applicable                       | Method 21,<br>Section 8.3.3.1,<br>Soap Test                                                | See footnote 2      |
| REX Booster<br>Station | Ohio River<br>System | 3/13/2019         | 7:25 AM                         | 8:35 AM                |                                        | ITC Certified OGI Thermographer.<br>More than five (5) years of<br>midstream surveying experience.                                                                                     | 33F, Mostly Cloudy,<br>2.5 mph                                                       | FLIR, GFx320<br>Serial No.<br>74900528 | No Deviations                                                 | Leak #1: Inlet Separator, Ball<br>Valve relief plug<br>Leak #2: Unit 4, fuel line<br>connector                                     | Leaks #1 & #2 were<br>repaired and verified<br>within 30 days.<br>Leak #1: Tightened<br>Leak #2: Re-taped and<br>tightened                                                                                        | Not Applicable                                               | Leaks were<br>repaired and<br>verified on<br>3/13/2019  | None                                                               | Not applicable                       | Method 21,<br>Section 8.3.3.1,<br>Soap Test                                                | See footnotes 1 & 2 |
| REX Booster<br>Station | Ohio River<br>System | 6/3/2019          | 11:00 AM                        | 12:15 PM               | 1                                      | ITC Certified OGI Thermographer.<br>More than five (5) years of<br>midstream surveying experience.                                                                                     | 60F, Sunny, 7.8<br>mph                                                               | FLIR, GFx320<br>Serial No.<br>74900528 | No Deviations                                                 | Leak: #1: Unit 204 lose<br>connection on instrument<br>plug<br>Leak: #2: Unit 201, header<br>Leak: #3: Unit 201, Prelube<br>filter | Leaks #1, #2, & #3 were repaired and verified within 30 days. Leak #1: Unit had to be taken down, then plug Cleamed, Re-taped and Retightened. Leak #2: Replaced seal and re-tightened Leak #3: Replaced selenoid | Not Applicable                                               | Leaks were<br>repaired and<br>verified on<br>6/4/2019   | None                                                               | Not applicable                       | Method 21,<br>Section 8.3.3.1,<br>Soap Test and<br>FLIR, GFx320<br>Serial No.<br>749005 28 | See footnotes 1 & 2 |

Footnotes:
REX Booster Footnote 1 No components are currently designated as DTM or UTM.

REX Booster Footnote 2 A daily verification check was conducted including a measurement of the maximum viewing distance as specified in the monitoring plan. The maximum viewing distance was not documented on the survey record; however, this is not a required record of NSPS 0000a (Monitoring Plan language will be updated). Station

> 10/29/2019 2 of 3

# **Pnuematic Controller Affected Facilities**

§60.5420(b)(5) and §60.5420a(b)(5)

| Controller ID Number                                                            | Facility Name                                                                                                                                                                                                                                                                                                                                                                                                                                       | State | Location | Make | Model | Month-Year<br>Constructed | Month-Year Replaced |  |
|---------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------|----------|------|-------|---------------------------|---------------------|--|
| <ul><li>i) The station did not cor</li><li>ii) The station did not co</li></ul> | EPORTING PERIOD 8/2/2018 TO 8/2/2019: The station did not commence construction of any gas-actuated continuous bleed pneumatic controller affected facilities during the reporting period. ) The station did not commence construction for any gas-actuated continuous bleed pneumatic controllers utilizing the functional need exemption of 40 CFR 60.5390(a) during the reporting period. i) No deviations occurred during the reporting period. |       |          |      |       |                           |                     |  |
|                                                                                 |                                                                                                                                                                                                                                                                                                                                                                                                                                                     |       |          |      |       |                           |                     |  |
|                                                                                 |                                                                                                                                                                                                                                                                                                                                                                                                                                                     |       |          |      |       |                           |                     |  |
|                                                                                 |                                                                                                                                                                                                                                                                                                                                                                                                                                                     |       |          |      |       |                           |                     |  |
|                                                                                 |                                                                                                                                                                                                                                                                                                                                                                                                                                                     |       |          |      |       |                           |                     |  |
|                                                                                 |                                                                                                                                                                                                                                                                                                                                                                                                                                                     |       |          |      |       |                           |                     |  |
|                                                                                 |                                                                                                                                                                                                                                                                                                                                                                                                                                                     |       |          |      |       |                           |                     |  |
|                                                                                 |                                                                                                                                                                                                                                                                                                                                                                                                                                                     |       |          |      |       |                           |                     |  |

Attachment C 3 of 3 10/29/2019

# ATTACHMENT - LDAR SURVEY RECORDS

| Company Legal Entity<br>Name:                              | Ohio River System, LLC                                                                                                                                                 |
|------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Facility Name:                                             | REX Booster Station                                                                                                                                                    |
| Name and Company of<br>Surveyor:                           | Allie Juarez (Trinity Consultants)                                                                                                                                     |
| Training and Experience of Surveyor: (attach if necessary) | Trained by an ITC Certified Thermographer, less than one (1) year of production/midstream surveying experience (including approx. 10 natural gas facility inspections) |

| Daily Verification Check Completed: (beginning of day, prior to surveys) | Yes No                    |
|--------------------------------------------------------------------------|---------------------------|
| Overall Survey Picture Taken with Camera: (needs date & lat/long)        | Yes No<br>File Name: 4503 |
| Maximum Wind Speed: (miles per hour)                                     | 4.3                       |
| <b>Ambient Temperature:</b> (deg F)                                      | 75.8                      |
| Measured Maximum Viewing Distance for Familiarization:                   | Yes No                    |
| Facility Status: (e.g., operating, partially shut down, etc.)            | Operating                 |
| Sky Conditions:                                                          | Clear<br>Partly Cloudy    |
|                                                                          | Overcast                  |

| Date of Survey: (MM/DD/YYYY) | 9/13/2018 |
|------------------------------|-----------|
|------------------------------|-----------|

| Survey Start Time: |          |
|--------------------|----------|
| (am / pm)          | 10:05 am |

|--|

| OGI Equipment Information:                |                                                                                                                                                                  |                               |                        |             |     |                |          |  |  |  |
|-------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------|------------------------|-------------|-----|----------------|----------|--|--|--|
| Manufacturer:                             | FLIR                                                                                                                                                             |                               | Model Number: GF320 Se |             |     | Serial Number: | 44401371 |  |  |  |
| All Component<br>Surveyed:                | ts (                                                                                                                                                             | Yes No                        | If no, explain:        | n/a         | n/a |                |          |  |  |  |
| Deviation(s) from Yes No Monitoring Plan: |                                                                                                                                                                  |                               | If yes, explain:       | n/a         | n/a |                |          |  |  |  |
| Comments:                                 | The maximum viewing distance (65 feet) was established, at the beginning of the survey, using a propane canister with an emission rate 1.1 scf/hr (60 grams/hr). |                               |                        |             |     |                |          |  |  |  |
| Additional Notes:                         |                                                                                                                                                                  | DTM componen                  |                        | n/a         | n/a |                |          |  |  |  |
|                                           |                                                                                                                                                                  | UTM componen  Components curr |                        | n/a<br>none |     |                |          |  |  |  |

|                      | Unit/Source:                                     | 204<br>Separator | Component Type (circle):                                                                | Valve / Flange<br>Connector / OEL<br>Pump Seal Other   | Description o                                   | f Location:                                           | Gauge                        |  |
|----------------------|--------------------------------------------------|------------------|-----------------------------------------------------------------------------------------|--------------------------------------------------------|-------------------------------------------------|-------------------------------------------------------|------------------------------|--|
|                      | Repair Attempted During<br>Initial Survey?       | YES NO           | Repair Verified During Initial Survey? (must affix identifier to component if 'NO')     | YES / NO NA                                            | Resurvey Cor<br>Successful Re<br>During Initial | pair                                                  | YES / NO NA                  |  |
|                      | Repair Method<br>Description:                    |                  |                                                                                         |                                                        |                                                 |                                                       |                              |  |
| Leak<br>Information: | Date Repaired<br>(if after initial survey):      | 9/14/2018        | Resurvey Confirmed (if after initial survey):                                           | YES / NO / NA                                          | Method for co                                   | _                                                     | OGI / Soap Test              |  |
|                      | Repair Method<br>Description:                    | Re-taped and T   | 'ightened                                                                               |                                                        |                                                 |                                                       |                              |  |
|                      | 1 -                                              | =                | ompleted because: technically infeasible,<br>shut-in, unsafe to repair during operation | YES / NO / NA                                          | _                                               | ental Approval REQUIRED)<br>out Delay of Repair Form) |                              |  |
|                      | Explanation if not repaired:                     |                  |                                                                                         |                                                        |                                                 |                                                       |                              |  |
|                      | Comments:                                        | Rex #1           |                                                                                         | Leak Image<br>File Name:                               | 4504                                            | Repair Ima<br>File Name:                              | _                            |  |
|                      | Unit/Source:                                     |                  | Component Type (circle):                                                                | Valve / Flange<br>Connector / OEL<br>Pump Seal / Other | Description o                                   | f Location:                                           |                              |  |
|                      | Repair Attempted During YES / NO Initial Survey? |                  | Repair Verified During Initial Survey? (must affix identifier to component if 'NO')     | YES / NO / NA                                          | Resurvey Cor<br>Successful Re<br>During Initial | pair                                                  | YES / NO / NA                |  |
|                      | Repair Method<br>Description:                    |                  |                                                                                         |                                                        | 35/                                             | <u> </u>                                              |                              |  |
| Leak<br>Information: | Date Repaired (if after initial survey):         |                  | Resurvey Confirmed (if after initial survey):                                           | YES / NO / NA                                          | Method for confirming repair/resurvey:          |                                                       | OGI / Soap Test              |  |
|                      | Repair Method<br>Description:                    |                  |                                                                                         |                                                        |                                                 |                                                       |                              |  |
|                      | *                                                | •                | ompleted because: technically infeasible,<br>shut-in, unsafe to repair during operation | YES / NO / NA                                          | (Environme<br>(Must fill ou                     |                                                       | ral REQUIRED)<br>epair Form) |  |
|                      | Explanation if not repaired:                     |                  |                                                                                         |                                                        |                                                 |                                                       |                              |  |
|                      | Comments:                                        |                  |                                                                                         | Leak Image<br>File Name:                               |                                                 | Repair Ima<br>File Name:                              | _                            |  |

| Company Legal Entity<br>Name:                              | Ohio River System, LLC                                                                                                                                               |
|------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Facility Name:                                             | REX Booster Station                                                                                                                                                  |
| Name and Company of<br>Surveyor:                           | Allie Juarez (Trinity Consultants)                                                                                                                                   |
| Training and Experience of Surveyor: (attach if necessary) | Trained by an ITC Certified Thermographer. Less than one (1) year of production/midstream surveying experience (including over 60 natural gas facility inspections). |

| Daily Verification Check Completed:<br>(beginning of day, prior to surveys) | Yes No                    |
|-----------------------------------------------------------------------------|---------------------------|
| Overall Survey Picture Taken with Camera: (needs date & lat/long)           | Yes No<br>File Name: 4812 |
| Maximum Wind Speed: (miles per hour)                                        | 2.3                       |
| <b>Ambient Temperature:</b> (deg F)                                         | 25.5                      |
| Measured Maximum Viewing Distance for Familiarization:                      | Yes No                    |
| Facility Status: (e.g., operating, partially shut down, etc.)               | Operating                 |
| Sky Conditions                                                              | Clear<br>Partly Cloudy    |
| Sky Conditions:                                                             | Overcast                  |

| Date of Survey:<br>(MM/DD/YYYY) | 12/10/2018 |
|---------------------------------|------------|
|---------------------------------|------------|

| Survey Start Time: (am / pm) | 8:55 am |
|------------------------------|---------|
|------------------------------|---------|

| Survey End Time: (am / pm) | 10:25 am |
|----------------------------|----------|
|----------------------------|----------|

| N3F3 0000a -                                | NSPS 0000a – Fugitive Emissions Monitoring Survey: Field Sheet |                                |                  |        |                               |  |  |  |  |  |
|---------------------------------------------|----------------------------------------------------------------|--------------------------------|------------------|--------|-------------------------------|--|--|--|--|--|
|                                             |                                                                |                                | OGI F            | Equip  | ment Information:             |  |  |  |  |  |
| Manufacturer:                               | FLIR                                                           | Model Number:                  |                  |        | GF320 Serial Number: 44401371 |  |  |  |  |  |
| All Component<br>Surveyed:                  | ts                                                             | Yes No                         | If no, explain:  |        | n/a                           |  |  |  |  |  |
| Deviation(s)<br>from<br>Monitoring<br>Plan: | Y                                                              | Yes No                         | If yes, explain: | n: n/a |                               |  |  |  |  |  |
| Comments:                                   |                                                                |                                |                  |        |                               |  |  |  |  |  |
|                                             |                                                                | DTM components  UTM components | -                | n/a    |                               |  |  |  |  |  |
|                                             |                                                                | Components currer              | ntly on DOR:     | non    | e                             |  |  |  |  |  |

|                      | Unit/Source:                               | BDV-401<br>(Phase 2<br>Suction BD) | Component Type (circle):                                                                | Valve / Flange<br>Connector / OEL<br>Pump Seal / Other | Description of Location:                                                             |                              | Plug on relief                                      |  |
|----------------------|--------------------------------------------|------------------------------------|-----------------------------------------------------------------------------------------|--------------------------------------------------------|--------------------------------------------------------------------------------------|------------------------------|-----------------------------------------------------|--|
|                      | Repair Attempted During Initial Survey?    | YES /NO                            | Repair Verified During Initial Survey?<br>(must affix identifier to component if 'NO')  | YES / NO / NA                                          | Resurvey Confirmed Successful Repair During Initial Survey?                          |                              | YES / NO / NA                                       |  |
|                      | Repair Method<br>Description:              | Re-taped and T                     | ightened                                                                                |                                                        |                                                                                      |                              |                                                     |  |
| Leak<br>Information: | Date Repaired (if after initial survey):   | 12/11/2018                         | Resurvey Confirmed (if after initial survey):                                           | YES/ NO / NA                                           | YES / NO / NA Method for confirming repair/resurvey:                                 |                              | OGI (Soap Test)                                     |  |
|                      | Repair Method<br>Description:              | Re-taped and Ti                    | ghtened                                                                                 |                                                        |                                                                                      |                              |                                                     |  |
|                      |                                            | •                                  | ompleted because: technically infeasible,<br>shut-in, unsafe to repair during operation | YES / NO / NA                                          | YES / NO / NA (Environmental Approval REQUIRED) (Must fill out Delay of Repair Form) |                              |                                                     |  |
|                      | Explanation if not repaired:               |                                    |                                                                                         |                                                        |                                                                                      |                              |                                                     |  |
|                      | Comments:                                  | Rex #1                             |                                                                                         | Leak Image<br>File Name:                               | 4813                                                                                 | Repair Image 4813 File Name: |                                                     |  |
|                      | Unit/Source:                               | Phase one suction filter separator | Component Type (circle):                                                                | Valve / Flange<br>Connector / OEL<br>Pump Seal / Other | Description of Location:                                                             |                              | Oil level sight<br>glass – top nipple<br>connection |  |
|                      | Repair Attempted<br>During Initial Survey? | YES /NO                            | Repair Verified During Initial Survey? (must affix identifier to component if 'NO')     | YES / NO / NA                                          | YES / NO / NA Resurvey Co<br>Successful Re<br>During Initia                          |                              | epair YES / NO / NA                                 |  |
|                      | Repair Method<br>Description:              |                                    |                                                                                         |                                                        |                                                                                      |                              |                                                     |  |
| Leak<br>Information: | Date Repaired (if after initial survey):   | 12/11/2018                         | Resurvey Confirmed (if after initial survey):                                           | YES/ NO / NA                                           | Method for confirming repair/resurvey:                                               |                              | OGI / Soap Test                                     |  |
|                      | Repair Method<br>Description:              | Re-taped and Ti                    | ghtened                                                                                 |                                                        |                                                                                      |                              |                                                     |  |
|                      |                                            | •                                  | ompleted because: technically infeasible,<br>shut-in, unsafe to repair during operation | YES / NO / NA                                          | YES / NO / NA (Environmental Approval REQUIRED) (Must fill out Delay of Repair Form) |                              |                                                     |  |
|                      | Explanation if not repaired:               |                                    |                                                                                         |                                                        |                                                                                      |                              |                                                     |  |
|                      | Comments:                                  | Rex #2                             |                                                                                         | Leak Image<br>File Name:                               | 4814                                                                                 | Repair Image<br>4 File Name: |                                                     |  |

# Fugitive Emissions Monitoring Survey: Field Sheet

|                                                                                                                                           |                                                                    |                                     | Daily Verification Che<br>(beginning of day, pri | •                             | Yes 🗸         | No |  |  |  |
|-------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------|-------------------------------------|--------------------------------------------------|-------------------------------|---------------|----|--|--|--|
| Company Legal<br>Entity:                                                                                                                  | Ohio River System LLC                                              |                                     | Overall Survey Pictur                            | e Taken with Camera:          | Yes 🗸         | No |  |  |  |
| Facility Name:                                                                                                                            | REX Booster Station                                                |                                     | Average Wind Speed                               | : (miles per hour)            | 2.5           |    |  |  |  |
| Name and Company of Surveyor:                                                                                                             | John Ecker                                                         |                                     | Ambient Temperatur                               | re: (deg F)                   | 33            | i  |  |  |  |
| Training and Experience of Surveyor:                                                                                                      | ITC Certified OGI Thern<br>than five (5) years of m<br>experience. |                                     | Measured Maximum<br>Familiarization:             | Viewing Distance for          | Yes 🗸         | No |  |  |  |
|                                                                                                                                           |                                                                    |                                     | Facility Status: (e.g., of shut down, etc.)      | operating, partially          | Operating     |    |  |  |  |
|                                                                                                                                           |                                                                    |                                     | Sky Conditions:                                  |                               | Mostly Cloudy |    |  |  |  |
|                                                                                                                                           |                                                                    |                                     |                                                  |                               | J             |    |  |  |  |
| Date of Survey:<br>(MM/DD/YYYY)                                                                                                           | 3/13/2019                                                          | 3/2019 Survey Start Time: (am / pm) |                                                  | Survey End Time:<br>(am / pm) | 8:35 a.m.     |    |  |  |  |
|                                                                                                                                           |                                                                    | OGI Equipment li                    | nformation.                                      |                               |               | 1  |  |  |  |
|                                                                                                                                           |                                                                    | • •                                 | mormation:                                       |                               |               |    |  |  |  |
| Manufacturer:                                                                                                                             | FLIR Model Number:                                                 |                                     | GFx320                                           | Serial Number:                | 74900528      |    |  |  |  |
| Observation Path Followed:                                                                                                                | Yes No No                                                          | If no, explain:                     |                                                  |                               |               |    |  |  |  |
| Deviation(s) from<br>Monitoring Plan:                                                                                                     | Yes No                                                             | If yes, explain:                    |                                                  |                               |               |    |  |  |  |
| Additional Notes: Operators arrived on site as survey was finishing. Had planned maintenance on unit 4 scheduled for afternoon on 3/13/19 |                                                                    |                                     |                                                  |                               |               |    |  |  |  |

**Fugitive Emissions Monitoring Survey:** Unit Source, Inlet Separator, Ball Valve relief plug Location, Component type: Repair Attempted Yes No Repair Verified Yes No **Resurvey Confirmed** Yes No **During Initial Survey? During Initial** Successful Repair During **|** Survey? **Initial Survey?** Date Repaired: Resurvey Confirmed: Soap Test Yes No Method for OGI 3/13/2019 (if after initial survey) (if after initial survey) confirming repair/resurvey: Leak Repair Method Tightened Information: Description: If not repaired within 15 days, repair cannot be completed because: technically infeasible, requires a vent blowdown/well shutdown/well shut-in, unsafe to repair during operation (Environmental Approval REQUIRED; Must fill out Delay of Repair Form) Explanation if not repaired: Additional Comments: Unit Source, Unit 4. fuel line connector Location, Component type: Repair Verified **Resurvey Confirmed** Yes Repair Attempted Yes No Yes No No During Initial Survey? Successful Repair During **During Initial** Survey? Initial Survey? Resurvey Confirmed: Soap Test Date Repaired: Yes No Method for OGI 3/13/2019 (if after initial survey) (if after initial survey) confirming **V** repair/resurvey: Leak Repair Method Re-taped and tightened Information: Description: If not repaired within 15 days, repair cannot be completed because: technically infeasible, requires a vent blowdown/well shutdown/well shut-in, unsafe to repair during operation (Environmental Approval REQUIRED; Must fill out Delay of Repair Form) Explanation if not repaired: Additional Comments:

| Fugitive Emissions Mon                | itoring Survey: NSPS - O                                    | 000a                         | PA GP-5                                       | Other 🗸                     |           |          |  |
|---------------------------------------|-------------------------------------------------------------|------------------------------|-----------------------------------------------|-----------------------------|-----------|----------|--|
|                                       |                                                             |                              | Daily Verification Ch<br>(beginning of day, p |                             | Yes 🗸     | No       |  |
| Company Legal<br>Entity:              | Ohio River System                                           |                              | Overall Survey Pictu                          | re Taken with Camera:       | Yes 🗸     | No       |  |
| Facility Name:                        | Rex Booster Station                                         |                              | Average Wind Speed                            | d: (miles per hour)         | 7.8       |          |  |
| Name and Company of Surveyor:         | John Ecker                                                  |                              | Ambient Temperatu                             | re: (deg F)                 | 6         | 0        |  |
| Training and Experience of Surveyor:  | ITC Certified OGI There than five (5) years of nexperience. |                              | Measured Maximun<br>Familiarization:          | n Viewing Distance for      | Yes 🚺     | No       |  |
|                                       |                                                             |                              | Facility Status: (e.g., shut down, etc.)      | operating, partially        | Operating |          |  |
|                                       |                                                             |                              | Sky Conditions:                               |                             | Sui       | nny      |  |
|                                       |                                                             |                              |                                               |                             |           |          |  |
| Date of Survey:<br>(MM/DD/YYYY)       | 6/3/2019                                                    | Survey Start Time: A.M. P.M. | 11:00                                         | Survey End Time:  A.M. P.M. | 12:15     |          |  |
|                                       |                                                             | 0015                         |                                               |                             |           | 7        |  |
|                                       |                                                             | OGI Equipment I              | nformation:                                   |                             | T         |          |  |
| Manufacturer:                         | acturer: FLIR Model Number:                                 |                              | GFx320                                        | GFx320 Serial Number: 7-    |           | 74900528 |  |
| ·                                     |                                                             |                              |                                               |                             |           |          |  |
| Observation Path Followed:            | Yes 🕢 No [                                                  | If no, explain:              |                                               |                             |           |          |  |
| Deviation(s) from<br>Monitoring Plan: | Yes No                                                      | If yes, explain:             |                                               |                             |           |          |  |
| Additional Notes:                     |                                                             |                              |                                               |                             |           |          |  |

**Fugitive Emissions Monitoring Survey:** Unit Source, UNIT 204 lose connection on instrument plug Location, Component type: Repair Attempted Yes No Repair Verified Yes No **Resurvey Confirmed** Yes No **During Initial During Initial Survey?** Successful Repair During Survey? **Initial Survey?** Date Repaired: Resurvey Confirmed: Soap Test Yes No Method for OGI 6/4/2019 (if after initial survey) (if after initial survey) confirming 1 repair/resurvey: Leak Repair Method Unit had to be taken down, then plug Cleaned, Re-taped and Re-tightened, Information: Description: If not repaired within 15 days, repair cannot be completed because: technically infeasible, requires a vent blowdown/well shutdown/well shut-in, unsafe to repair during operation (Environmental Approval REQUIRED; Must fill out Delay of Repair Form) Explanation if not repaired: Additional Comments: Unit Source, Unit 201, header Location, Component type: Repair Verified **Resurvey Confirmed** Yes Repair Attempted Yes No Yes No No During Initial Survey? Successful Repair During **During Initial** Survey? Initial Survey? Resurvey Confirmed: Soap Test Date Repaired: Yes Method for OGI No 6/4/2019 (if after initial survey) (if after initial survey) confirming **√** repair/resurvey: Leak Repair Method Replaced seal and re-tightened Information: Description: If not repaired within 15 days, repair cannot be completed because: technically infeasible, requires a vent blowdown/well shutdown/well shut-in, unsafe to repair during operation (Environmental Approval REQUIRED; Must fill out Delay of Repair Form) Explanation if not repaired: Additional Comments:

| <b>Fugitive Emiss</b> | ions Monitoring Surv         | ey:              |          |            |                                       |               |          |         |                              |              |                |
|-----------------------|------------------------------|------------------|----------|------------|---------------------------------------|---------------|----------|---------|------------------------------|--------------|----------------|
|                       | Unit Source,                 | LINIT 2          | 01 Preh  | ube filter |                                       |               |          |         |                              |              |                |
|                       | Location,                    | 01111 2          | 01, 1101 | abe inter  |                                       |               |          |         |                              |              |                |
|                       | Component type:              |                  |          |            |                                       |               |          |         |                              |              |                |
|                       | Repair Attempted             | Ye               | es:      | No         | Repair Verified                       | Yes           | No       | Ī       | Resurvey Confirmed           | Yes          | No             |
|                       | During Initial Survey        | /?   <u> </u>    | 7        |            | During Initial                        |               |          | 7       | Successful Repair During     |              |                |
|                       |                              | /                |          |            | Survey?                               |               | <b>✓</b> | J       | Initial Survey?              |              | <u> </u>       |
|                       | Date Repaired:               | 6/4/             | /2019    |            | Resurvey Confirmed:                   | Yes           | N        | 10      | Method for                   | OGI          | Soap Test      |
|                       | (if after initial survey)    |                  |          |            | (if after initial survey)             | <b>V</b>      |          |         | confirming                   |              |                |
| Leak<br>Information:  |                              |                  |          |            |                                       | V             |          |         | repair/resurvey:             |              |                |
|                       | Repair Method                | Replace          | d selenc | oid        |                                       |               |          |         |                              |              |                |
|                       | Description:                 | rescription:     |          |            |                                       |               |          |         |                              |              |                |
|                       |                              |                  |          |            |                                       |               |          |         |                              |              |                |
|                       | 1 -                          | -                |          |            | · · · · · · · · · · · · · · · · · · · |               |          | -       | es a vent blowdown/well shut | down/well sl | hut-in, unsafe |
|                       |                              | ition <b>(Er</b> | nviron   | mental A   | Approval REQUIRED; Must               | fill out Dela | y of Ke  | pair Fo | rm)                          |              |                |
|                       | Explanation if not repaired: |                  |          |            |                                       |               |          |         |                              |              |                |
|                       | repaired:                    |                  |          |            |                                       |               |          |         |                              |              |                |
| 1                     | Additional                   |                  |          |            |                                       |               |          |         |                              |              |                |
|                       | Comments:                    |                  |          |            |                                       |               |          |         |                              |              |                |
|                       | Unit Source,                 |                  |          |            |                                       |               |          |         |                              |              |                |
|                       | Location,                    |                  |          |            |                                       |               |          |         |                              |              |                |
|                       | Component type:              |                  |          |            |                                       |               |          |         |                              |              |                |
|                       | Repair Attempted             | Ye               | es.      | No         | Repair Verified                       | Yes           | No       |         | Resurvey Confirmed           | Yes          | No             |
|                       | During Initial Survey        | /?               |          |            | During Initial                        |               |          | 7       | Successful Repair During     |              |                |
|                       |                              | L                |          |            | Survey?                               |               | <u> </u> |         | Initial Survey?              |              |                |
|                       | Date Repaired:               |                  |          |            | Resurvey Confirmed:                   | Yes           | N        | Ю       | Method for                   | OGI          | Soap Test      |
|                       | (if after initial survey)    |                  |          |            | (if after initial survey)             |               | 1        |         | confirming                   |              |                |
| Leak                  |                              |                  |          |            |                                       |               |          |         | repair/resurvey:             |              |                |
| Information:          | Repair Method                |                  |          |            |                                       |               |          |         |                              |              |                |
|                       | Description:                 |                  |          |            |                                       |               |          |         |                              |              |                |
|                       |                              |                  |          |            |                                       |               |          |         |                              |              |                |
|                       | 1 -                          | -                |          |            | •                                     |               |          |         | es a vent blowdown/well shut | down/well si | hut-in, unsafe |
|                       | Explanation if not           | ition (Er        | nviron   | mentai A   | Approval REQUIRED; Must               | Till out Dela | у от ке  | pair Fo | rm)                          |              |                |
|                       | repaired:                    |                  |          |            |                                       |               |          |         |                              |              |                |
|                       | repaired.                    |                  |          |            |                                       |               |          |         |                              |              |                |
|                       | Additional                   |                  |          |            |                                       |               |          |         |                              |              |                |
|                       | Comments:                    |                  |          |            |                                       |               |          |         |                              |              |                |

| <b>Fugitive Emiss</b> | ions Monitoring Survey    | y:          |                  |                             |               |             |                       |                         |              |                |
|-----------------------|---------------------------|-------------|------------------|-----------------------------|---------------|-------------|-----------------------|-------------------------|--------------|----------------|
|                       | Unit Source,              |             |                  |                             |               |             |                       |                         |              |                |
|                       | Location,                 |             |                  |                             |               |             |                       |                         |              |                |
|                       | Component type:           |             |                  |                             |               |             |                       |                         |              |                |
|                       | Repair Attempted          | Yes         | No               | Repair Verified             | Yes           | No          | Res                   | urvey Confirmed         | Yes          | No             |
|                       | During Initial Survey?    |             |                  |                             |               |             | cessful Repair During |                         |              |                |
|                       |                           |             |                  | Survey?                     |               |             | 1                     | ial Survey?             |              |                |
|                       | Date Repaired:            |             |                  | Resurvey Confirmed:         | Yes           | No          |                       | Method for              | OGI          | Soap Test      |
| Leak                  | (if after initial survey) |             |                  | (if after initial survey)   |               | ]   [       |                       | confirming              |              |                |
|                       | Donois Mathod             |             |                  |                             |               | <u> </u>    |                       | repair/resurvey:        |              | <u></u>        |
| Information:          | Repair Method             |             |                  |                             |               |             |                       |                         |              |                |
|                       | Description:              |             |                  |                             |               |             |                       |                         |              |                |
|                       |                           |             |                  | t be completed because: ted |               |             | -                     | vent blowdown/well shut | down/well sl | hut-in, unsafe |
|                       | ļ                         | on (Enviror | mental A         | Approval REQUIRED; Must     | fill out Dela | y of Repai  | r Form)               |                         |              |                |
|                       | Explanation if not        |             |                  |                             |               |             |                       |                         |              |                |
|                       | repaired:                 |             |                  |                             |               |             |                       |                         |              |                |
|                       | Additional                |             |                  |                             |               |             |                       |                         |              |                |
|                       | Comments:                 |             |                  |                             |               |             |                       |                         |              |                |
|                       | Unit Source,              |             |                  |                             |               |             |                       |                         |              |                |
|                       | Location ,                |             |                  |                             |               |             |                       |                         |              |                |
|                       | Component type:           |             |                  |                             |               |             |                       |                         |              |                |
|                       | Repair Attempted          | Yes         | No               | Repair Verified             | Yes           | No          | Res                   | urvey Confirmed         | Yes          | No             |
|                       | During Initial Survey?    |             |                  | During Initial              |               |             | Suc                   | cessful Repair During   |              |                |
|                       |                           |             |                  | Survey?                     | <u> </u>      |             | Init                  | ial Survey?             |              |                |
|                       | Date Repaired:            |             |                  | Resurvey Confirmed:         | Yes           | No          |                       | Method for              | OGI          | Soap Test      |
|                       | (if after initial survey) |             |                  | (if after initial survey)   |               | 7   [       |                       | confirming              |              |                |
| Leak                  |                           |             |                  |                             |               |             |                       | repair/resurvey:        |              |                |
| Information:          | Repair Method             |             |                  |                             |               |             |                       |                         |              |                |
|                       | Description:              |             |                  |                             |               |             |                       |                         |              |                |
|                       | 15                        |             | •                |                             |               |             |                       |                         |              |                |
|                       | 1 -                       |             |                  | be completed because: ted   |               |             | •                     | vent blowdown/well shut | down/well st | hut-ın, unsafe |
|                       | Explanation if not        | on (Enviror | imentai <i>i</i> | Approval REQUIRED; Must     | mi out Deia   | iy or Kepai | r Form)               |                         |              |                |
|                       | repaired:                 |             |                  |                             |               |             |                       |                         |              |                |
|                       | Tepaireu.                 |             |                  |                             |               |             |                       |                         |              |                |
|                       | Additional                |             |                  |                             |               |             |                       |                         |              |                |
|                       | Comments:                 |             |                  |                             |               |             |                       |                         |              |                |